




VIBO®
Wire processing

Portata massima:
Maximum load:
Charge maxi:
Maximale belastbarkeit:
Carga maxima:




Istruzioni di montaggio
Assembling instructions
Notice de montage
Montageanleitung
Manual de montaje



SMACE...

30 min	1	+	10
		8	



**PRIMA DI COMINCIARE,
VEDERE I CONSIGLI DI
MONTAGGIO**







BEFORE STARTING, REFER
TO THE ASSEMBLING
ADVICE IN ANNEX

AVANT DE COMMENCER, SE
REPORTER AUX CONSEILS
DE MONTAGE EN ANNEXE




VOR DIE MONTAGE, BITTE
BEILIEGENDE
ANWEISUNGEN FOLGEN

ANTES DE EMPEZAR
CONSULTE LOS CONSEJOS
PARA EL MONTAJE



A x 1	B x 1	C x 1	D x 1	E x 1	F x 1	4 x 16 G x 18
M5 H x 1	I x 2	L3, L3, L4, L1, L2 L x 1	Ø5 M x 1	4 x 16 N x 19		




IV






V




1



VI




Ⓡ VII





Ⓡ VIII

C




Ⓡ IX


D




(X)





(XI)




(XII)




XIII




XIV





(XV)




(XVI)



OPTIONAL



A



B

